William MCGlinn

NEWPORT HISTORIC DISTRICT COMMISSION DEPARTMENT OF ZONING & INSPECTION

HOC DEC. 13

APPLICATION FOR CERTIFICATION OF APPROPRIATENESS

Additional INFO-

ADDITIONAL INFORMATION

WILLIAM MCGLINN
32 SCHOOL STREET, UNIT 3

WINDOW REPLACEMENT

FEBRUARY 8, 2021



Window Assessment

12/9/20

Holly & Peter Murphy 32 School Street, Newport, RI Hollymurphy16@comcast.net 1-860-227-2124

Re: 32 School Street Condos, Newport

On January 13, 2020, Heritage Restoration, Inc. surveyed 13 windows on 32 School Street, Newport, RI.

The house was built perhaps around 1880, although has been heavily modified, upgraded, and add to over the course of its life. The Tax Assessor's card identifies the house as a 1920, but the exterior features, window locks, weight and pully operating systems, and sash profiles all resemble late 19th century style, technology and systems.

The windows are double hung wood weight and pulleys. Each window either neglected, heavily painted and caulked, weathered, or severely modified. Some of the window sashes were


decorative small lights surrounding a large light of glass (Image right) but at some point the muntins were removed to make the sash a 1 over 1. We discovered ghosts of the profiles and the muntin tenon.

Window 1.7

If you have any questions or comments on the assessment, please feel free to let me know.


Robert Cagnetta, President







			Windo	ws
#	Lights Now	Lights Originally	Condition	
			General	Notes
1.1	1 over 1	15 over 15	Poor	Finishes and glaze poor, not functional
1.2	1 over 1	15 over 15	Fair	Finishes and glaze poor, not functional
1.3	1 over 1	15 over 15	Fair	Finishes and glaze poor, not functional
1.4	1 over 1	15 over 15	Fair	Finishes and glaze poor, not functional
1.5	6 over 6	6 over 6	Poor	Missing weather stripping. Overpaint. Broken stop
1.6	6 over 6	6 over 6	Poor	Broken glass, overpaint, failing glaze
1.7	15 over 15	15 over 15	Poor	Not functional
2.1	1 over 1	15 over 15	Fair	Painted shut, perhaps replaced since sas construction different than 1st floor
2.2	2 over 2	?	Fair	Painted shut, perhaps replaced since sas construction different than 1st floor
2.3	1 over 1	15 over 15	Fair	Painted shut, perhaps replaced since sast construction different than 1st floor
2.4	2 over 2	?	Fair	Now a fire escape, replaced
2.5	6 over 6	6 over 6	Poor	Broken glass, overpaint, failing glaze
2.6	15 over 15	15 over 15		Finishes and glaze poor



SCHOOL

----- Original Message -----

From: Robert Cagnetta <rob@heritagerestoration.net>

To: Hollymurphy16@comcast.net

Date: 01/27/2021 9:56 AM

Subject: Re: Window Assessment

Holly,

You could certainly use our report to justify window replacement by their condition and the fact that they were altered. But our Window Assessments only present observations to leave treatment to the HDC. The HDC's respect is based on the fact these reports present facts the board can use to make their decision based on their own criteria.

So no, I cannot make a judgement.

Robert Cagnetta President



8 Robin Street Providence, RI 02908 401.932.1985

Rob@HeritageRestoration.net www.HeritageRestoration.net Instagram @HeritageRestoration From: tomb@hbsri.com

To: hollymurphy16@comcast.net

Date: 01/21/2021 1:46 PM

Subject: FW: 32 School Street, Newport

Holly,

Good afternoon, I hope that you are doing well.

Attached are the proposals and installation numbers for 32 School Street, Newport, RI, Condos 1 &3.

I have broken the files up so that the rear windows, dining room windows, and 2nd floor windows are all separate. Also, please note that the prices on the "install" proposals all include the window pricing rolled into them.

My opinion is that the windows on the first and second floor look as if they were replaced in the 30's or thereabouts, and then updated possibly in the 50's with some metal weather stripping. I can say that this is my best guess as they don't appear to be original.

One of the details that need to be addressed is that the new sash kits are primed, they are not prefinished. Humphrey's does not do finish painting.

If you would like to move forward or have any questions, please call me @ 508-431-0885.

Thanks Holly,
-Tom



Tom Brooks
Architectural Representative
401.816.5755

Build With The .com

Building Supply 590 Main Road - Tiverton RI

Paint Center 750 Aquidneck Ave - Middletown RI

Window and Door Design Gallery 8 Coddington Hwy - Middletown RI From: Danielle Erickson < DErickson@renewalsne.com>

Date: December 29, 2020 at 8:39:57 AM EST **To:** Steve Martin < <u>SMartin@renewalsne.com</u>> **Cc:** Tom Bonura < <u>TBonura@renewalsne.com</u>>

Subject: Historic Jobs in Newport

Good morning Steve,

Here are some addresses of recently completed Historic Jobs in Newport (that include windows):

15 Hammersmith Rd., Unit 4

6CSF, 3FWF, 7CDF, 6 Entry and 4

Patio doors

15 East St

4GTF

173 Rhode Island Ave

1 Entry, 2DBI

12 Almy Street

3DBI

Thank you!

Danielle Erickson

Sales Support Coordinator
Renewal by Andersen of Southern New England

10 Reservoir Road Smithfield, RI 02917 401 450-0727







Window Assessment

12/9/20

Holly & Peter Murphy 32 School Street, Newport, RI Hollymurphy16@comcast.net 1-860-227-2124

Re: 32 School Street Condos, Newport

On January 13, 2020, Heritage Restoration, Inc. surveyed 13 windows on 32 School Street, Newport, RI.

The house was built perhaps around 1880, although has been heavily modified, upgraded, and add to over the course of its life. The Tax Assessor's card identifies the house as a 1920, but the exterior features, window locks, weight and pully operating systems, and sash profiles all resemble late 19th century style, technology and systems.

The windows are double hung wood weight and pulleys. Each window either neglected, heavily painted and caulked, weathered, or severely modified. Some of the window sashes were

decorative small lights surrounding a large light of glass (Image right) but at some point the muntins were removed to make the sash a 1 over 1. We discovered ghosts of the profiles and the muntin tenon.


Window 1.7

glass (Image right) but at some point the

If you have any questions or comments on the assessment, please feel free to let me know.


Robert Cagnetta, President







			Windo	ws
#	Lights Now	Lights Originally	Condition	
			General	Notes
1.1	1 over 1	15 over 15	Poor	Finishes and glaze poor, not functional
1.2	1 over 1	15 over 15	Fair	Finishes and glaze poor, not functional
1.3	1 over 1	15 over 15	Fair	Finishes and glaze poor, not functional
1.4	1 over 1	15 over 15	Fair	Finishes and glaze poor, not functional
1.5	6 over 6	6 over 6	Poor	Missing weather stripping. Overpaint. Broken stop
1.6	6 over 6	6 over 6	Poor	Broken glass, overpaint, failing glaze
1.7	15 over 15	15 over 15	Poor	Not functional
2.1	1 over 1	15 over 15	Fair	Painted shut, perhaps replaced since sas construction different than 1st floor
2.2	2 over 2	?	Fair	Painted shut, perhaps replaced since sas construction different than 1st floor
2.3	1 over 1	15 over 15	Fair	Painted shut, perhaps replaced since sas construction different than 1st floor
2.4	2 over 2	?	Fair	Now a fire escape, replaced
2.5	6 over 6	6 over 6	Poor	Broken glass, overpaint, failing glaze
2.6	15 over 15	15 over 15		Finishes and glaze poor



SCHOOL

----- Original Message -----

From: Robert Cagnetta <rob@heritagerestoration.net>

To: Hollymurphy16@comcast.net

Date: 01/27/2021 9:56 AM

Subject: Re: Window Assessment

Holly,

You could certainly use our report to justify window replacement by their condition and the fact that they were altered. But our Window Assessments only present observations to leave treatment to the HDC. The HDC's respect is based on the fact these reports present facts the board can use to make their decision based on their own criteria.

So no, I cannot make a judgement.

Robert Cagnetta President



8 Robin Street Providence, RI 02908 401.932.1985

Rob@HeritageRestoration.net www.HeritageRestoration.net Instagram @HeritageRestoration From: tomb@hbsri.com

To: hollymurphy16@comcast.net

Date: 01/21/2021 1:46 PM

Subject: FW: 32 School Street, Newport

Holly,

Good afternoon, I hope that you are doing well.

Attached are the proposals and installation numbers for 32 School Street, Newport, RI, Condos 1 &3.

I have broken the files up so that the rear windows, dining room windows, and 2nd floor windows are all separate. Also, please note that the prices on the "install" proposals all include the window pricing rolled into them.

My opinion is that the windows on the first and second floor look as if they were replaced in the 30's or thereabouts, and then updated possibly in the 50's with some metal weather stripping. I can say that this is my best guess as they don't appear to be original.

One of the details that need to be addressed is that the new sash kits are primed, they are not prefinished. Humphrey's does not do finish painting.

If you would like to move forward or have any questions, please call me @ 508-431-0885.

Thanks Holly, -Tom



Tom Brooks
Architectural Representative
401.816.5755

Building Supply 590 Main Road -Tiverton RI

Paint Center 750 Aquidneck Ave - Middletown RI

Window and Door Design Gallery 8 Coddington Hwy - Middletown RI From: Danielle Erickson < DErickson@renewalsne.com >

Date: December 29, 2020 at 8:39:57 AM EST **To:** Steve Martin < SMartin@renewalsne.com > **Cc:** Tom Bonura < TBonura@renewalsne.com >

Subject: Historic Jobs in Newport

Good morning Steve,

Here are some addresses of recently completed Historic Jobs in Newport (that include windows):

15 Hammersmith Rd., Unit 4

6CSF, 3FWF, 7CDF, 6 Entry and 4

Patio doors

15 East St

4GTF

173 Rhode Island Ave

1 Entry, 2DBI

12 Almy Street

3DBI

Thank you!

Danielle Erickson

Sales Support Coordinator
Renewal by Andersen of Southern New England


10 Reservoir Road Smithfield, RI 02917 401 450-0727





OUBLE HUNG WINDOWS

* * * * * 142,890 Ratings















Timeless, elegant, simple, versatile - there's a reason double-hung windows are North America's first choice. But at Renewal by Andersen, we believe there's always room to push perfection a little further. Or a lot further. With our next generation double-hung window, we've created our most extraordinary, most beautiful and highest performing double-hung window to date.

Must Set Appointment by February 28th!

BUY ONE

(WINDOW

AND/OR

PATIO

DOOR)

GET ONE 40% OFF*

Plus No Money

Down, No

Interest and No

Payments for 12

Months!*

SEE OFFER **DETAILS**

(/forms/schedule-

a-consultation)

A beautiful, high performing window is only part of the equation. We believe that living with our windows should be as painless as having them professionally installed.

Renewal by Andersen's double-hung opens smoothly and allows for quick one-handed tilting of both sash for easy cleaning, and is one of the easiest to operate on the market!

Sash options:

- · Equal (upper and lower sashes are equal size)
- · Cottage-style (lower sash is larger than upper)
- · Oriel (upper sash larger than lower)
- Available with up to nearly a 6' tall fixed upper

Renewal by Andersen® double-hung windows are an excellent choice for restoration and renovation projects where historic accuracy is important. They are also well-suited for rooms facing walkways, porches, or patios, as they do not protrude into the space.

*This product may not be available in all colors and options. Contact us to schedule an in-home consultation for specific options in your area.

SCHEDULE A CONSULTATION (/FORMS/SCHEDULE-A-**CONSULTATION#)**

DESIGN THIS WINDOW

VIEW PRODUCT IN AUGMENTED REALITY (HTTPS://WWW.RENEWALBYANDERSEN.COM/AR-WITH-RENEWAL-BY-ANDERSEN? RBA 1=AR CLICK)

Let's Talk 904-980-0446

Projects Near You 595 in your Neighborhood

Social 1,497 Must Set Appointment by February 28th!

(tel:+19049800446)

CALL US

VIEW MAP (/MAP)

Facebook Likes

Buy One (Window and/or Patio Dger) Get Qng 40% Off*

LIKE US (/FRUSING MONS/EDAN/ENS-(HTTPS://WWW.FACEBOOK.COM/RENEWAL PInterest and No Payments for NCITI)
12 Months!*



ABOUT OUR WINDOWS

Durable. Beautiful. Custom crafted, made to order, and professionally installed.

First Name

finergy-efficient replacement windows from Renewal by Andersen ទុងវិធីស្វែ ទី Wood, with the ស្រីស ការ៉ាក់ទេកិន្តិ ខែ ខែឯក្រទេខិត្ត ប៉ុំក្រៀងទី

offer the elegance, strength and CONSULTATI

Investigate window styles below, or browse our different color (/windows-doors/options/window-colors), frame (/signature-service/fibrex-composite-material), grille (/windows-doors/options/grille-options), and hardware options (/windows-doors/options/window-hardware) to find the right style for your home. Ready to get started right now? Set up a free appointment (/forms/schedule-a-consultation) to work with one of our design consultants.

Made from the Andersen-exclusive Fibrex® composite material (/signature-service/fibrex-composite-material), your new windows will stand the test of time+... and look great doing it. What's more, you'll have peace of mind knowing they were installed by one of our own crews of master installers—true craftspeople who have experience replacing windows in homes of all shapes, sizes, and styles.

Learn more about our installation process and the dedicated individuals (/signature-service/professional-installation) who will be working in your home.

Pick a performance metric: efficiency, strength and durability, maintenance, beauty...whichever factor is most important to you (and we hope they all are!), your Renewal by Andersen replacement windows can make a difference.

Energy Efficiency

Superior thermal insulating properties helps your home stay warmer in winter and cooler in summer and can help you save money on your energy bills (/signature-service/energy-efficiency).

Plus, 40% of the raw material by weight used to make Fibrex® material is reclaimed wood fiber. Our windows are available with glass options (/windows-doors/options/glass) that make them ENERGY STAR® certified—so not only will your home stay more comfortable, you can help keep your corner of the world is just a little bit greener.

Strength and Durability

Twice as strong as vinyl, Fibrex® material means weathertight seals stay weathertight. Its durable nature (/signature-service/20-year-durability-study) means that it can stand up to even the most extreme temperature swings, maintaining its stability and rigidity in all climates.

Low Maintenance

Your Renewal by Andersen® windows are warranted (/homeowners/warranty) not to flake, rust, blister, peel, crack, pit or corrode.+ And years down the road, they will be as easy to operate as the day they are installed.*

Beauty

The strength of Fibrex® material means narrower frames; narrower frames mean more glass—and more view. Plus, the extrusion process allows us to craft your windows to any shape—meaning you can match the architectural style of your home...or define a new look (/windows-doors/replacement-windows/specialty).

The process also fuses the color into the material, offering you a wide palette of long-lasting colors+ (/windows-doors/options/window-colors) to choose from—including dark exterior colors not found with most other replacement windows.

With stainable wood interiors (/windows-doors/options/window-colors) including oak, maple, and engineered pine, 11 hardware finishes (/windows-doors/options/window-hardware), and a variety of grille patterns (/windows-doors/options/grille-options), including colonial, prairie, and custom-designed, you can match your new windows to your home's current architecture, change your look, or complete a historically accurate renovation.


Need help deciding? Looking for a quote? Schedule a free in-home window consultation (/forms/schedule-a-consultation) with our window design experts or visit one of our showrooms (/map).

[+] See (https://cm.renewalbyandersen.com//sitecore/service/notfound.aspx? item=web%3a%7bB4595C75-BBC4-4988-976F-87704BE1AF6B%7d%40en&aitrk=organic)limited warranty (/homeowners/warranty) for details

[*] Based on testing of 10 double-hung units per ASTM E2068, 20 years after installation.









SAMPLE WINDOW IN PLACE

Here's a link to "DB white Historic WIDE BAR FDL half screen Truscene-7.jpeg" in my Dropbox:









Here's a link to "Historic farmhouse before and after



FEBRUARY 8, 2021
WILLIAM AND KATHY MCGLINN
32 SCHOOL STREET
CONDO #3, SECOND FLOOR
PHOTOS OF INTERIOR WINDOWS

PICTURE NUMBERS CORRESPOND WITH NUMBERS ON HERITAGE RESTORATION DIAGRAM

Window Assessment

12/9/20

Holly & Peter Murphy 32 School Street, Newport, RI Hollymurphy16@comcast.net 1-860-227-2124

Re: 32 School Street Condos, Newport

On January 13, 2020, Heritage Restoration, Inc. surveyed 13 windows on 32 School Street, Newport, RI.


The house was built perhaps around 1880, although has been heavily modified, upgraded, and add to over the course of its life. The Tax Assessor's card identifies the house as a 1920, but the exterior features, window locks, weight and pully operating systems, and sash profiles all resemble late 19th century style, technology and systems.


The windows are double hung wood weight and pulleys. Each window either neglected, heavily painted and caulked, weathered, or severely modified. Some of the window sashes were Window 1.7

decorative small lights surrounding a large light of glass (Image right) but the muntins were removed to make the sashes 1 over 1's. We discovered ghosts of the profiles and the muntin tenon.

If you have any questions or comments on the assessment, please feel free to let me know.

Robert Cagnetta, President






MCGUNN 2nd Floor Condo #3



8 Robin Street Providence, RI 02908 P/F (401) 490-0888 www.heritagerestoration.net

			Windo	ws
#	Lights Now	Lights Originally	Condition	
			General	Notes
1.1	1 over 1	15 over 15	Poor	Finishes and glaze poor, not functional
1.2	1 over 1	15 over 15	Fair	Finishes and glaze poor, not functional
1.3	1 over 1	15 over 15	Fair	Finishes and glaze poor, not functional
1.4	1 over 1	15 over 15	Fair	Finishes and glaze poor, not functional
1.5	6 over 6	6 over 6	Poor	Missing weather stripping. Overpaint. Broken stop
1.6	6 over 6	6 over 6	Poor	Broken glass, overpaint, failing glaze
1.7	15 over 15	15 over 15	Poor	Not functional
2.1	1 over 1	15 over 15	Fair	Painted shut, perhaps replaced since sas construction different than 1st floor
2.2	2 over 2	?	Fair	Painted shut, perhaps replaced since sas construction different than 1st floor
2.3	1 over 1	15 over 15	Fair	Painted shut, perhaps replaced since sas construction different than 1st floor
2.4	2 over 2	?	Fair	Now a fire escape, replaced
2.5	6 over 6	6 over 6	Poor	Broken glass, overpaint, failing glaze
2.6	15 over 15	15 over 15		Finishes and glaze poor



----- Original Message -----

From: Robert Cagnetta <rob@heritagerestoration.net>

To: Hollymurphy16@comcast.net

Date: 01/27/2021 9:56 AM

Subject: Re: Window Assessment

Holly,

You could certainly use our report to justify window replacement by their condition and the fact that they were altered. But our Window Assessments only present observations to leave treatment to the HDC. The HDC's respect is based on the fact these reports present facts the board can use to make their decision based on their own criteria.

So no, I cannot make a judgement.


Robert Cagnetta President



8 Robin Street Providence, RI 02908 401.932.1985

Rob@HeritageRestoration.net www.HeritageRestoration.net Instagram @HeritageRestoration











2.6





