**51 PRAIRIE AVENUE** 

## COA APPLICATION TO REPLACE 6 WINDOWS ADDITIONAL MATERIAL IN RESPONSE TO JANUARY 19, 2021 MEETING

BIRDZELL

FEBRUARY 16, 2021

## **TOPIC**


- 1. WINDOW INVENTORY-Pages 2-9
- 2. 90 RHODE ISLAND AVENUE-Pages 10, 11
- 3. NEIGHBORHOOD-Pages 12,13
- 4. Window manufacturers other than the one in the application
  - a. We considered and are actively considering manufacturers other that the one specified in the application.
  - b. The manufacturer in the application was selected based on product suitability and availability. Availability may have changed with time for both the specified and other manufacturers.


DESCRIPTION OF 51 PRAIRIE AVENUE (from January 19, 2018 National Register of Historic Places Registration Form, emphasis added)


51 (NC) Lansing Zabriskie Barn (1889-90 et seq.; J. D. Johnston, architect-builder): A much altered square-plan, 1½-story, deck-on-hip-roof building with clapboard on the east and south walls, random-course-cast-stone ashlar on north and west walls, asymmetrical fenestration, barrel-vault sunbonnet gables above east and west elevations, round-head dormers above south, west, and north elevations, and off-center chimney near the lower edge of roof's west slope. This was originally the barn for the property at 90 Rhode Island Avenue (q.v.).

Garage (ca 1985): A 2-stall, hip-roof garage near the property's northeast corner.


FEBRARY 1				
51 PRAIRIE AVENUE				
BIRDZELL				
		WINDOW INVENTORY		
		LOCATION	DESCRIPTION	PICTURE PAGE #
	1	UPPER LEVEL NORTH EAST	Single hung, circle top window located in dormer; 4 panes in upper sash under circle top	3,4,5
			Top sash has been permanently closed with blocks in window jamb for at least 45 years	
			Lower sash has been modified so that it has two panes instead of 8	
	2	UPPER LEVEL NORTH WEST	Single hung, circle top window located in dormer; 4 panes in upper sash under circle top	6
			Top sash has been permanently closed with blocks in window jamb for at least 45 years	
			Lower sash has been modified so that it has two panes instead of 8	
			Lower sash has been further modified so that it opens inward on left side hinges; it can not be raised	
	3	UPPER LEVEL REAR	Single hung, circle top window located in dormer; 4 panes in upper sash under circle top	7
			Top sash has been permanently closed with blocks in window jamb for at least 45 years	
			Lower sash has 8 panes	
	4	UPPER LEVEL SOUTH	Single hung, circle top window located in dormer; 4 panes in upper sash under circle top	8
		0.1.2.1.22.23.30.111	Top sash has been permanently closed with blocks in window jamb for at least 45 years	
			Lower sash has 8 panes	
			Both upper and lower sash are very warped	
			The window is currently closed with duct tape	
			The William is currently closed with duct tape	
		LOWER LEVEL NORTH EAST		
	5 & 6	& NORTH WEST	Double hung rectangular window; 8 panes in lower sash; 8 panes in upper sash	9









Block in window jamb holding upper sash closed














City of Newport, RI February 5, 2021



## **Map Theme Legends**

Historic District

